



Adjust correct position of hall sensors via back EMF before connecting motor to driver!

							KELLY CONTROLS, LLC		
Mark	Subarea	Signatory	Date	10/2010	Hall/Phase timing (120°)				
Design	Steven	Stand	Fany	modification	Number	Proportion	V1.0		
Assessor	Daniel	Authorize	Steven	Sum					
Technics									